



HEAVY VEHICLE INSPECTION AND MAINTENANCE SOFTWARE

Material Hoist Pre-Shutdown Checklist

Hoist ID: MH-7132
Make/Model: GEDA 500Z/ZP
Hours: 1320
Date: 2025-05-02
Operator: Lara Scott
Supervisor: Aaron Davis

No	Inspection Item	Status	Remark
1	Platform positioned at ground level or designated	OK / NA	
2	Platform cleared of all materials and debris	OK / NA	
3	Platform gates closed and secured	OK / NA	
4	Platform floor condition (no damage, structural in	OK / NA	
5	Enclosure panels/fencing (secure, no damage)	OK / NA	
6	Load rating signs (present, legible)	OK / NA	
7	Toe boards and railings (secure, no damage)	OK / NA	
8	Platform lighting (off, no damage)	OK / NA	
9	Emergency stop button (reset position)	OK / NA	
10	Motor(s) powered down completely	OK / NA	

Signature: _____

Barcode: []