



www.heavyvehicleinspection.com

Excavator Daily Inspection Checklist

Mobile Crane - Pre-Operation Inspection Info

Crane No.: MC-7731
Make/Model: Terex RT 90
Odometer: 45,672 mi
Project: Eastport Lift Yard
Date: 2025-05-01
Operator: George Walker
Supervisor: Amira Shaikh

Checklist Items (Sample)

	Inspection Point	Status	Notes
☐	Tires (condition, inflation, tread depth, damage)	OK / Issue	
☐	Wheels, rims, lug nuts (damage, tightness, rust tr	OK / Issue	
☐	Steering system (function, free play, hydraulic le	OK / Issue	
☐	Braking system (air pressure, function, adjustment	OK / Issue	
☐	Engine (oil level, coolant, unusual noises)	OK / Issue	
☐	Fuel system (level, leaks, cap secure)	OK / Issue	
☐	Transmission/transfer case (fluid levels, leaks)	OK / Issue	
☐	Air system (leaks, moisture drains, pressure build	OK / Issue	
☐	Electrical system (lights, indicators, horn, wirin	OK / Issue	
☐	Frame and structural members (cracks, damage)	OK / Issue	

Use Checklist Online: <https://heavyvehicleinspection.com/portal/signup>

Inspector Signature: _____

Barcode: _____